



27 April 2009

Competitor Bulletin #2 (Reissued)- Lanark Highlands Forest Rally, 9 May 2009

LHFR Competitor Bulletin #2 is modified as a result of CARS Bulletin 09-2, April 14, 2009.

Competitors are reminded of a new rule for 2009:

CARS GCR and RR 2009, Section VIII: Service Crews

9.

Modify wording of first paragraph to read:

"All Service Crews must have at least one fire extinguisher with a minimum UL rating of 40BC or two fire extinguishers with a minimum UL rating of 20BC each in their respective service area."

Where a fire service is not present, service crews must carry at least one fire extinguisher with a minimum UL rating of 10BC, other than the fire extinguisher on board the competition vehicle, to all refueling zones and remote/optional refueling zones.

If requested by an official, evidence must be produced that fire extinguishers have been purchased or recharged within the preceding two years.

Craig Hamm
LHFR Clerk of the Course